


PARTS


① X 1	A.M6*20 X 4	
② X 1	B.M6*40 X 10	
③ X 2	C. X 10	
④ X 1	M6	
⑤ X 1	D.X 1	
⑥ X 1	M6	
⑦ x5		

NOTICE:
 EVERY 6 MONTHS, PLEASE MAKE SURE
 ALL BOLTS, SCREWS AND KNOBS ARE
 FULLY TIGHTENED TO ENSURE
 STABILITY.

STEP 1




STEP 2




B  4PCS
 C  4PCS
 D 

STEP 3



B  6PCS
 C  6PCS
 D 

STEP 4



A  4PCS
 D 

STEP 5



STEP 6

